DMV Lane Technician Observation Report

DMV Technician: Sieve Groven Positio	on: 1 or 2				
Station: Dover Date: 9-22-14 Time:					
Vehicle Make: Messes Town Model Soss	Year 1992				
GVWR: Fuel Type: G Registration N	Registration Number: 28353				
Auditor: Covert / Overt (circle one)					
	VALUE VI. S. VALUE VI.				
	YES	NO	N/A		
1. Did technician check vehicle paper work and verify VIN number?	-				
2. Was Emissions testing required?		-			
a) Was Emissions testing performed using OBD?			_		
b) Was Emissions testing performed using Analyzer Probe?			_		
c) Was Emissions testing performed using Paddle(s)?			-		
d) Was Emissions testing performed using Clip?			_		
3. Was Catalytic Converter inspection required?					
a) Was Catalytic Converter inspection performed?			_		
4. Was Fuel Tank pressure testing required?		-			
a) Was Fuel Tank pressure testing performed?		_			
5. Was Fuel Cap pressure testing required?		_			
a) Was Fuel Cap pressure testing performed?		-			
6. Is this test a Re-check from a prior failure?		~			
a) Which re-check test is being performed? 1 2 3 (circle one)			<u></u>		
b) If this is re-check #3, was repair paperwork verified for waiver?					
New Castle and Kent Counties Only					
7. Was Two-Speed Idle testing required?					
a) Was Two-Speed Idle testing performed?			_		
			S-135U-277-531		
Sussex County Only					
8. Was Curb Idle testing required?		-			
a) Was Curb Idle testing performed?		Herewill To July 1	-		
Comment:					
4	- No. of the last				
* NO ADAPTERS TO PERFORM TEST - CORRECTLY VERIFIED #					
CNECKED BY TECHNICIAN *					
		70.00			
3					

DMV Lane Technician Observation Report

	osition: 1 or 2			
Station: Date: 9-22-14 Time: 2:20				
Vehicle Make: Dove Model	Year 2004			
	Number: C11401			
Auditor: Covert / Overt (circle one)				
		P		
	YES	NO	N/A	
1. Did technician check vehicle paper work and verify VIN number?				
2. Was Emissions testing required?	_			
a) Was Emissions testing performed using OBD?	_			
b) Was Emissions testing performed using Analyzer Probe?		-		
c) Was Emissions testing performed using Paddle(s)?		_		
d) Was Emissions testing performed using Clip?		-		
3. Was Catalytic Converter inspection required?	NI.	_		
a) Was Catalytic Converter inspection performed?			-	
4. Was Fuel Tank pressure testing required?		-		
a) Was Fuel Tank pressure testing performed?			-	
5. Was Fuel Cap pressure testing required?		_		
a) Was Fuel Cap pressure testing performed?		-		
6. Is this test a Re-check from a prior failure?		-	JIESED OF THE SET	
a) Which re-check test is being performed? 1 2 3 (circle one)			_	
b) If this is re-check #3, was repair paperwork verified for waiver?			_	
	VALUE VALUE IN THE PARTY IN THE	55357500		
New Castle and Kent Counties Only				
7. Was Two-Speed Idle testing required?	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	-		
a) Was Two-Speed Idle testing performed?			_	
Sussex County Only				
8. Was Curb Idle testing required?		-		
a) Was Curb Idle testing performed?			_	
Comment:				

Original 08/06/2009